

Note on Using Real-Time OSeS RI78V4 and RX78K0R

When using the real-time OSeS RI78V4 and RX78K0R for the 78K0R MCUs and RL78 family MCUs, take note of the following problem:

- With interrupts being enabled after the `iunl_cpu` or `unl_cpu` service calls issued
-

1. Products and Versions Concerned

- (1) RI78V4 V1.00.00 through V1.00.01
- (2) RX78K0R V4.30 package (V4.30 kernel) and earlier

2. Description

If the interrupt handler issues the `iloc_cpu` or `loc_cpu` service calls to lock the CPU and afterward issues the `iunl_cpu` or `unl_cpu` service calls to unlock it, all the requested interrupts will be enabled after the `iunl_cpu` or `unl_cpu` call is serviced.

As a result, if any interrupt in the same priority level as or a lower one than the currently handled interrupt is requested after the `iunl_cpu` or `unl_cpu` call is serviced, the interrupt may be handled as a member of multiple interrupts.

3. Conditions

This problem arises if the following conditions are all satisfied:

- (1) The interrupt handler, including a cyclic handler, issues the `iloc_cpu` or `loc_cpu` service calls and afterward issues the `iunl_cpu` or `unl_cpu` service calls.
- (2) In addition to the interrupt handler in (1), another interrupt handler, including a timer handler and a cyclic handler, is used.

Note, however, that even if all the above conditions have been satisfied, this problem may not arise depending on the timing of interrupt requests.

4. Workarounds

To avoid this problem, do either of the following in the interrupt

handler (including a cyclic handler):

- (1) Replace `iloc_cpu` and `loc_cpu` with the Interrupt Disable `DI()`.
- (2) Replace `iunl_cpu` and `unl_cpu` with the Interrupt Enable `EI()`.

Note that because all the interrupts are disabled during the period from the issue of `DI()` to that of `EI()`, neither of the above methods can be used if any interrupt with a higher priority than the currently handled one should be acknowledged.

5. Schedule of Fixing Problem

As to RI78V4, we plan to fix this problem in its next version, but as to RX78K0R, we have no plan to fix the problem.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.