

Notes on Using a Real-Time OS--RX850V4--for the V850 of MCUs

When you use real-time OS RX850V4, take note of the following problems:

- With cyclic handlers in ready state not cyclically operating (No. 6)
- With an intended memory block not taken out of the variable-sized memory pool (No. 7)

Here, the number at the end of each item is a consecutive number of the problems in RX850V4. For problems No.1 through No.5, see:

<http://tool-support.renesas.com/eng/toolnews/rx850v4.html>

This Web site will be opened on and after July 21, 2011.

The above URL is one of our global sites.

1. Problem with Cyclic Handlers in Operational State Not Cyclically Operating (No. 6)

1.1 Versions Concerned

The kernel of RX850V4 V4.30 and earlier

(In the RX850V4 package, V4.42 and earlier are concerned.)

1.2 Descriptions

If the `sta_cyc` service call is issued from any interrupt handlers to the cyclic handler whose attribute is not `TA_PHS`, another cyclic handler to which the `sta_cyc` service call has not been issued may not operate cyclically.

If you refer to information about any cyclic handler that cannot operate cyclically, `TCS_STA` is displayed which indicates the cyclic handler is in the operational state.

To refer to information about cyclic handlers, use the `ref_cyc` service call or the RD850V4 task debugger.

1.3 Conditions

This problem arises if the following conditions are both satisfied:

- (1) While the cyclic handler "cychdrX" whose attribute is not TA_PHS is in the operational state, a base clock timer interrupt request of the OS is acknowledged.
- (2) While the interrupt request in (1) is handled, interrupt handler "inthdrA" issues the sta_cyc service call to "cychdrX" in (1)

Note, however, that even if the above conditions are both satisfied, this problem may not arise depending on when interrupts are requested or how data is processed within the OS.

1.4 Workaround

Do not issue the sta_cyc service call from an interrupt handler to a cyclic handler whose attribute is not TA_PHS.

1.5 Schedule of Fixing the Problem

We plan to fix this problem in the next version of the product.

2. Problem with an Intended Memory Block Not Taken out of the Variable-Sized Memory Pool (No. 7)

2.1 Versions Concerned

The kernel of RX850V4 V4.30 and earlier
(In the RX850V4 package, V4.42 and earlier are concerned.)

2.2 Descriptions

The get_mpl or tget_mpl service call may not return the intended address of the memory blocks taken out of the variable-sized memory pool.

2.3 Conditions

This problem arises if the following conditions are both satisfied:

- (1) Two or more tasks issue get_mpl or tget_mpl service calls to a variable-sized memory pool "mplX", which attribute is "TA_TPRI".
- (2) While a get_mpl or tget_mpl service call in (1) is handled, The interrupt handler "inthdrA" issues the chg_pri or ichg_pri service call to the task which issued a get_mpl or tget_mpl service call in (1).

Note, however, that even if the above conditions are both satisfied, this problem may not arise depending on how data is processed within the OS.

2.4 Workaround

Make changes to the code so that either or both of the above conditions are not satisfied.

2.5 Schedule of Fixing the Problem

We plan to fix this problem in the next version of the product.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.