

RENESAS TOOL NEWS on December 11, 2015: 151211/tn2

## Code Generator Plug-in for the e<sup>2</sup> studio Update

We are updating the e<sup>2</sup> studio (Code Generator Plug-in) from V2.0.2 to V2.1.1

For an overview of the product, see the following page:

[https://www.renesas.com/cg\\_p](https://www.renesas.com/cg_p)

---

### 1. Applicable Products

- e<sup>2</sup> studio V4.0.1.018, (Code Generator Plug-in, V2.0.2) and earlier revisions

### 2. Descriptions of Revision

#### 2.1 Addition of Supported MCUs

The following group has been added to the set of supported MCUs.

- RX family: RX130 group

#### 2.2 Problem Fixed

The following problems announced on RENESAS TOOL NEWS have been fixed.

##### (1) RENESAS TOOL NEWS Document No.150516/tn1

###### 4. 12-bit A/D Converter (S12ADC)

(Applicable MCUs: RX64M and RX71M groups)

###### 5. 12-bit D/A Converter (R12DA)

(Applicable MCUs: RX64M and RX71M groups)

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150516tn1>

Note1: This problem also applies to the Code Generator Plug-in for the e<sup>2</sup> studio.

Note2: Numbers 1 to 3 are already fixed.

##### (2) RENESAS TOOL NEWS Document No.150716/tn1

###### 1. Bus Settings

(Applicable MCUs: RX64M and RX71M groups)

###### 2. Code Generated for the Clock Generation Circuit (HOCO Operation)

(Applicable MCUs: RX111 and RX113 groups)

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150716tn1>

(3) RENESAS TOOL NEWS Document No.150807/tn3

- Complementary PWM mode setting of the MTU  
(Applicable MCUs: RX230 and RX231 groups)

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150807tn3>

(4) RENESAS TOOL NEWS Document No.150901/tn2

- Interrupts when the MTU is set for complementary PWM mode  
(Applicable MCUs: RX23T group, RX230 and RX231 groups, RX110, RX111, and RX113 groups)

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150901tn2>

(5) RENESAS TOOL NEWS Document No.151101/tn4

- 3. Setting of the data transfer controller (DTC)  
(Applicable MCUs: RX71M, RX64M, RX23T, RX230, RX231, and RX113 groups)

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=151101tn4>

Note: Numbers 1 and 2 will be fixed in the next version.

(6) RENESAS TOOL NEWS Document No.151201/tn3

- Using the Multi-Function Pin Controller (MPC) to Select Functions of the PAn Pins  
(Applicable MCUs: RX113 group)

For details of the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=151201tn3>

### 3. Updating Your Product

Refer to RENESAS TOOL NEWS document number 151211/tn1 "3. Updating Your Product" for details of how to update the e<sup>2</sup> studio. This information will be available on the Web from December 15, 2015.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=151211tn1>

Note that only updating the Code Generator Plug-in is not possible.

---

**[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.