# **RENESAS** Tool News

### RENESAS TOOL NEWS on April 1, 2005: RSO-E10A-USB-050401D

## A Note on Using the E10A-USB and E10A Emulators

Please take note of the problems shown below in using the E10A-USB and E10A Emulators, which are used for specific groups in the SuperH RISC engine family of MCUs.

#### 1. Products Concerned

- E10A-USB and E10A emulators for the SH7618 group, SH7600 series, SuperH RISC engine family
- (2) E10A-USB emulator for the SH7619 group, SH7600 series, SuperH RISC engine family

Product Types:

Product	Product types
E10A-USB	HS0005KCU01H (WithoutAUD) HS0005KCU02H (WithAUD)
E10A	HS7618KCM01H (PCMCIA) HS7618KCI01H (PCI)

### 2. Problems

2.1 In the Case Where the E10A-USB, or the E10A of the PCMCIA Type Used When the HIF boot mode is used for the user system, "COMMUNICATION TIMEOUT ERROR" arises, and the connection between the user system and the emulator cannot be established if HIF booting is not completed within 30 seconds after a Reset input is supplied to the user system.

So, be sure to complete HIF booting within 30 seconds upon Reset.

2.2 In the Case Where the E10A of the PCI Type Used When the HIF boot mode is used for the user system, this emulator does not function.

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.