R20TS0079EJ0100

Rev.1.00 Oct. 01, 2016

[Upgrade to revision]

CS+ Code Generator for RX

e² studio (Code Generator Plug-in)

AP4 Coding Assistance Tool for RX

Outline

We are revising the CS+ Code Generator for RX, e² studio (Code Generator Plug-in), and AP4 coding assistance tool for RX devices, and will adjust the respective version numbers from V1.10.00 to V1.11.00, V2.3.0 to V2.5.0, and V1.09.00 to V1.10.00.

Products and Versions to Be Updated

- All revisions up to V1.10.00 of the CS+ Code Generator for RX
- All revisions up to V5.1.0 of the e² studio (with V2.4.0 of the Code Generator Plug-in)
- All revisions up to V1.09.00 of the AP4 coding assistance tool for RX

Description of Revisions

The following points are to be upgraded. Refer to the Release Notes for details.

- CS+ Code Generator for RX V1.11.00 Release Note (this document will be released on October 5.) https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut3851
- e² studio Code Generator Plug-in
 - e² studio V5.2.0 Release Note (this document will be released on October 5.)

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut3907

AP4 for RX V1.10.00 Release Note (this document will be released on October 5.)

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut3848

2.1 **Description of Modification**

The problems regarding the points below have been fixed.

- (1) Renesas Tool News document number R20TS0039EJ0100
 - 1. Serial communications interface SCI6


Applicable MCUs: RX231 group (100-pin products) and RX230 group (100-pin products)

2. Saving settings for the code generator

Applicable MCUs: RX110, RX111, RX113, RX130, RX230, RX231, RX23T, RX24T, RX64M, and RX71M groups

For details of the problem, refer to the URL below.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0039





3. Updating Your Product

The method of updating depends on the product you are using.

Refer to the following for the details. The updates are free of charge.

3.1 Updating the CS+ Code Generator for RX

Refer to section 3, Updating Your Product, document number R20TS0077EJ0100 for the method of updating CS+. This information will be available from October 5.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0077

3.2 Updating the e² studio Code Generator Plug-in

Refer to section 3, Updating Your Product, document number R20TS0084EJ0100 for the method of updating e² studio. This information will be available from October 5.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0084

You cannot update the Code Generator Plug-in alone.

3.3 Updating the AP4 Coding Assistance Tool for RX

Download the installer from the URL below to install the program. The installer is scheduled for posting on October 5. http://www.renesas.com/applilet_download

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Oct. 01, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

■Inquiry

http://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2016. Renesas Electronics Corporation. All rights reserved.