# [Upgrade to revision]

R20TS0282EJ0100 Rev.1.00 Mar. 1, 2018

## RX Family TCP/IP for Embedded system M3S-T4-Tiny

# Firmware Integration Technology V.2.07 Release 00

### **Outline**

We will be revising the RX family TCP/IP for embedded system M3S-T4-Tiny Firmware Integration Technology from V.2.06 to V.2.07.

For details of the product, refer to the following URL.

https://www.renesas.com/mw/t4

### **Product and Version to Be Updated**

RX Family TCP/IP for Embedded system M3S-T4-Tiny Firmware Integration Technology V.2.06

For details of the RX family TCP/IP for embedded system M3S-T4-Tiny Firmware Integration Technology V.2.06, refer to the following URL.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20an0051

RX Family TCP/IP for Embedded system M3S-T4-Tiny Introduction Guide Firmware Integration Technology

### **Items Revised**

The major revision points are as follows.

#### 2.1 Items to Be Newly Supported

Support for the Smart Configurator has been added.

For details about the tool, refer to the URLs below.

https://www.renesas.com/smart-configurator

Smart Configurator product page

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20an0451

Renesas e<sup>2</sup> studio Smart Configurator User Guide

#### 2.2 **Description of Modification**

- The following problem that was informed in RENESAS TOOL NEWS Document No. 160201tn2\_e (the previous Document No. 160201/tn2) has been fixed.
  - Failure in cancelling UDP transmission and reception

For details about the problem, refer to the following URL.

https://www.renesas.com/search/keyword-search.html#q=160201tn2

Page 1 of 3 RENESAS Mar. 1, 2018

- ➤ The following problem that was informed in RENESAS TOOL NEWS Document No. R20TS0227EJ0100 has been fixed.
  - 1. Ping Reply Packets

For details about the problem, refer to the following URL.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0227

### 3. Updating Your Product

### 3.1 Online Updating

> For updating with the Smart Configurator

Refer to the following application note.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20an0451

Renesas e<sup>2</sup> studio Smart Configurator User Guide

For updating with FIT

Refer to the following application note.

https://www.renesas.com/search/keyword-search.html#genre=document&q=r01an1723

RX Family Adding Firmware Integration Technology Modules to Projects

## 3.2 Downloading Package from our Web site

Download the RX Family TCP/IP for Embedded system M3S-T4-Tiny Introduction Guide Firmware Integration Technology from our Web site below.

Download page for the TCP/IP M3S-T4-Tiny FIT modules

https://www.renesas.com/mw/t4#sampleCodes

### **Revision History**

		Description	
Rev.	Date	Page	Summary
1.00	Mar. 1, 2018	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

### ■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.1