

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for Intersil Product ISL8014\***

**Refer to:  
PA10015**

**Date: February 17, 2010**

February 17, 2010

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil Product ISL8014\***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL8014\* products. The changes consist of the following:

- i) Updated sheets 2, 3, and 13 to indicate EN is not permitted to be directly connected to VIN and to provide recommendations for EN operation/configuration as it relates to VIN.
- ii) Updated the Typical Application Diagram on sheet 3 to remove EN to VIN connection.
- iii) Updated the Block Diagram on sheet 4 to remove the inverter.
- iv) Updated the UVLO section on sheet 14 to include the use of a resistor divider network across the EN pin.

The updated data sheet, FN6576 dated November 23, 2009, is included as a separate attachment with the changes shaded in yellow and/or circled in red.

Products Affected:

ISL8014IRZ	ISL8014IRZ-TS2378	ISL8014IRZ-TS2715
ISL8014IRZ-T	ISL8014IRZ-TS2568	ISL8014IRZS2715

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

*Jon Brewster*

Intersil Corporation

PA10015

CC: J. Touvell V. Toussaint V. Vaidya J. Xiao M. Casino