

RENESAS TOOL NEWS on May 1, 2005: RSO-E8_2-050501D

A Note on Using the E8 Emulator Software V.2.01 Release 00

Please take note of the following problem in using the emulator software for the E8 on-chip debugging emulator:

- On loading user programs onto the emulator
-

1. Description

Consider the case where the M16C/Tiny, M16C/62P E8 emulator debugger V.1.00.00, which is included in the E8 emulator software V.2.01 Release 00, is used for debugging user programs.

If a user program is loaded onto the emulator, an error may arise depending on target MCUs.

2. Condition

This problem occurs if any program written in the ROM area from FE000h to FEFFFh is loaded onto the emulator with any of the following MCUs being targeted for debugging:

M30280FA, M30281FA, M30290FA, M30290FC, M30291FA, and M30291FC

3. Solution

This problem has already been resolved in the E8 emulator software V.2.02 Release 00. So please download this from **HERE** and update yours to it.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.