

RENESAS TOOL NEWS on March 16, 2010: 100316/tn4

A Note on Using Flash Development Toolkit --With Selecting a Programming Destination--

Please take note of the problem described below in using Flash Development Toolkit.

- With selecting a programming destination
-

1. Product and Versions Concerned

Flash Development Toolkit

V.4.04 Release 00 and V.4.05 Release 00

2. MCUs Involved

The following MCUs of the M16C/50 series are involved in this problem:

(1) In the M16C/56 group

R5F35676 and R5F35680

(2) In the M16C/5L group

R5F35L80, R5F35L83, R5F35L86, and R5F35L8E

3. Problem

If you select "Data Flash" as a programming destination in any of the MCUs in Section 2, programming cannot be performed because these MCUs are not provided with any data flash areas. This problem arises from an error of displaying incorrect programming destinations. So do not select "Data Flash" in these MCUs.

4. Schedule of Fixing the Problem

We plan to fix this problem in Flash Development Toolkit V.4.05 Release 01, which will be released on April 20, 2010.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be

included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.