

RENESAS TOOL NEWS on April 1, 2014: 140401/tn2

Application Leading Tool for RL78 Revised

We have revised the Application Leading Tool for RL78 from V1.01.00 to V1.02.00.

1. Descriptions of Revision

1.1 Problem fixed

The following problem has been fixed:

- When the timer KB20 is in Use (RL78/L13 group)

For details of the problem, see RENESAS TOOL NEWS Document No. 131016/tn3

<https://www.renesas.com/search/keyword-search.html#genre=document&q=131016tn3>

1.2 Removal of the watch error correction function from the real-time clock

(target MCUs: RL78/L13, RL78/G1C, and RL78/L1C groups)

The watch error correction function of the real-time clock has been removed.

If watch errors of the real-time clock require correction, please consult your local Renesas Electronics marketing office or distributor.

2. Updating Your Product

Download the installer of the product from the following URL:

https://www.renesas.com/applilet_download

The installer will be published on this site on April 7.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.