

RENESAS TOOL NEWS on August 1, 2014: 140801/tn3

Application Leading Tool for RL78 Revised

We have revised the Application Leading Tool for RL78 from V1.02.00 to V1.03.00.

1. Descriptions of Revision

(1) Device Support

The following RL78 family MCUs have been added to the support line:

In the RL78/G10 group:

Products with 16 pins

(2) Problem Fixed

The following problem, of which we informed you in RENESAS TOOL NEWS Document No. 140416/tn7, has been fixed:

- With using the remote control carrier wave mask signal in the RL78/L13 group

For details of the problem, see the following page:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=140416tn7>

2. Updating Your Product

Download the installer of the product from the following URL:

https://www.renesas.com/applilet_download

The installer will be available on this site from August 5.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.