

RENESAS TOOL NEWS on April 16, 2015: 150416/tn5

Revision and Change to the Name of the Application Leading Tool for RX

Application Leading Tool for RX: from V1.04.00 to V1.05.00

The name will be changed from "Application Leading Tool for RX" to "AP4 for RX".

1. Description of Revision

Revised from V1.04.00 to V1.05.00

The following revisions will be made in V1.05.00.

(a) Addition of Supported MCUs

The following group has been added to the set of supported MCUs.

- RX family: RX71M group

(b) The problem on the following point announced in a cautionary note (issue No. 140416/tn6 of Renesas Tool News) will be fixed.

With generating code for the IAR Embedded Workbench for Renesas RX devices (hereafter called EWRX) from IAR Systems (target: RX110 and RX111 groups)

For that issue of Tool News, giving more information on the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=140416tn6>

(c) The problem on the following point announced in a cautionary note (issue No. 140816/tn5 of Renesas Tool News) will be fixed.

With setting of the multi-function timer pulse unit (MTU) and 16-bit timer pulse unit (TPU) (target: RX111 and RX64M groups)

For that issue of Tool News, giving more information on the problem, refer to the URL below.

(d) The problem on the following point announced in a cautionary note (issue No. 141216/tn4 of Renesas Tool News) will be fixed.

- Settings for clocks in the output code
(applicable products: RX64M group)
- Bus settings
(applicable products: RX64M group)

For that issue of Tool News, giving more information on the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=141216tn4>

(e) The problem on the following point announced in a cautionary note (issue No. 150301/tn3 of Renesas Tool News) will be fixed.

- Multifunction Timer Pulse Unit 3
(Applicable products: RX64M group)
- Serial Communications Interface
(Applicable products: RX110, RX111, RX113 and RX64M groups)

For that issue of Tool News, giving more information on the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150301tn3>

2. Obtaining the Product

Download the installer from the URL below to install the program.

The program will be available from April 20.

https://www.renesas.com/applilet_download

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.