

RENESAS TOOL NEWS on June 16, 2015: 150616/tn9

Revision of the AP4 Coding Assistance Tool for RX

We are revising the AP4 for RX from V1.05.00 to V1.06.00.

1. Descriptions of Revision

(a) Addition of supported MCUs

The following group has been added to the set of supported MCUs.

RX family: RX23T group

(b) The problems on the following points announced in a cautionary note (issue No. 150516/tn3 of Renesas Tool News) will be fixed.

The problems regarding the points below will be fixed. Numbers 4 and 5 are not yet fixed.

1. Code Generated for the Clock Generation Circuit (PLL Circuit Operation)

Applicable products: RX111 and RX113 groups

2. Bus Settings

Applicable products: RX64M and RX71M groups

3. 16-bit Timer Pulse Unit (TPUa) and Multifunction Timer Pulse Unit 3 (MTU3a)

Applicable products: RX64M and RX71M groups

For details of the problems, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150516tn3>

2. Obtaining the Product

Download the installer from the URL below to install the program.

The program will be available from June 22.

https://www.renesas.com/applilet_download

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may

be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.