
PRODUCT CHANGE NOTICE

**Alternate Test Site for the
Listed Intersil EL7562* and
EL7566* Products**

**Refer to:
PCN13032**

Date: April 19, 2013

April 19, 2013

To: Our Valued Intersil Customer

Subject: **Alternate Test Site for the Listed Intersil EL7562* and EL7566* Products –
Intersil (ISP) Palm Bay, Florida**

This notice is to inform you that Intersil is using its facility located in Palm Bay, Florida as an alternate site for performing final electrical screening (package level testing) of the listed EL7562* and EL7566* packaged products. This action will expand current capabilities and capacities to optimize Intersil's ability to meet customer's delivery requirements. As of this notice, all site-specific verification activities are complete.

Products affected:

EL7562CUZ-T13S2705	EL7566DREZ	EL7566DREZ-T7
--------------------	------------	---------------

The Intersil (ISP) facility is ISO 9001:2008 and ISO 14001:2004 certified for testing of packaged products. The following summarizes the activities that were conducted prior to production release to confirm there is no impact to form, fit, function, or interchangeability of the product.

- Intersil supplied test software and product specific hardware is used at ISP.
- The test equipment validation plan involves the testing of control units and a correlation lot of each product type at the ISP and current facility.
 - Control units were tested at the current test site and retested at ISP, their performance recorded, and the results analyzed to validate the set-up.
 - A correlation lot was tested at the current test site and retested at ISP. The test results from each site were compared.
 - Continuous monitoring and comparison of the data from lots processed at multiple sites are an ongoing function of the responsible product engineers.

Product affected by this change is identifiable via Intersil's internal traceability system

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product that has been electrically screened at either the current or ISP site beginning *ninety* days from the date of this notification or earlier with approval.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jeff Touvell
Intersil Corporation

PCN13032

CC: J. Touvell J. Kline J. Duncombe B. Sampath C. Chiraphanda