Microcontroller Technical Information

	Document No.	ZMT	-F35-11-0004	1/1
ID78K0-QB	Date issued	April 19, 2011		
78K0 Integrated Debugger	Issued by	MCU Tool Product Marketing Department		
		MCU	MCU Software Division	
Upgrade		MCU Business Unit		
		Renesas Electronics Corporation		
Related documents:	Document		Usage restriction	
ID78K0-QB Integrated Debugger Ver. 3.10	classification		√ Upgrade	
Operation User's Manual: U19611EJ1V0UM00			Document modification	
			Other notification	

1. Target product and version

Product	Outline	Old Version	New Version
ID78K0-QB	78K0 integrated debugger for IECUBE, MINICUBE, MINICUBE2	V3.20 or earlier	V3.21

2. Upgrade details

The major changes in ID78K0-QB V3.21 are listed below. For details, see *ID78K0-QB 78K0 Integrated Debugger - Usage Restrictions* (ZMT-F35-11-0003).

Specifications

No.	Removed Restrictions	Affected Product
92	Restrictions on Main Clock setting "System", 8.00MHz, 16.00MHz	MINICUBE2
93	Restrictions on break of sub-clock operation	Common
95	Restrictions on the setting of 16-bit timer X0/X1 compare registers 0 to 3 for 78K0/lx2	MINICUBE2

Common: Items common to IECUBE, MINICUBE, and MINICUBE2

3. How to upgrade

Download the latest product from the Renesas Electronics website. Install the tool according to the procedure described in the document posted on the same download page.

URL: English version:http://www2.renesas.com/micro/en/ods/ \rightarrow Click Version-up Service.Japanese version:http://www2.renesas.com/micro/ja/ods/

4. Upgrade start date

The upgraded product can be downloaded from the website starting on April 26, 2011.

This schedule may be shifted somewhat.