

Safety related modules / components

| Type Designation / Description | SW Revision | MD5 signature | | Report-No.: | Certification Status |
|--|-------------|-------------------------------|----------------------------------|--------------------|----------------------|
| Renesas FSoE Application Software for EWRX Compiler RTK0EF0081F01001SJ | 1.00a | FSOE_api.h | 86188b6a34e1654eee5a930a114c9ffa | 968/FSP 2104.00/20 | <i>Valid</i> |
| | | FSOE_hal.h | 75008f666a820d5c67e82ede8c134434 | | |
| | | FSOE_lib_if.h | 139fc6d53e66e75bfb72e7e40ba5ea55 | | |
| | | FSOE_type_define.h | dbe94a5f15d7cbb138325e072021fbaa | | |
| | | FSOE_interface.c | b1cbad250de3d94143eacaa9c6fa7dbc | | |
| | | FSOEApp.a (for RX v2 core) | 7cb21e8242ce381c0bdbd47ee55e5900 | | |
| | | FSOEApp.a (for RX v3 core) | 4d942077be1b7e24b10adeca245e9404 | | |
| Renesas FSoE Application Software for CC-RX Compiler RTK0EF0080F01001SJ | 1.00b | FSOE_api.h | 86188b6a34e1654eee5a930a114c9ffa | | <i>Valid</i> |
| | | FSOE_hal.h | 75008f666a820d5c67e82ede8c134434 | | |
| | | FSOE_lib_if.h | 139fc6d53e66e75bfb72e7e40ba5ea55 | | |
| | | FSOE_type_define.h | dbe94a5f15d7cbb138325e072021fbaa | | |
| | | FSOE_interface.c | b1cbad250de3d94143eacaa9c6fa7dbc | | |
| | | FSOEApp.rel | 25ba9c0c0f9b2c838b56cfcfc983174e | | |

NOTE:

Those files which are not listed above are treated as sample code. These must be configured by the integrator according to the user documentations and needs to be verified/validated during the integration.



Revision List of Renesas Electronics Corporation
referred to on Certificate No.: 968/FSP 2104.00/20
Renesas FSoE Application Software



Safety Manual / User documentation

| Document No. | Revision | Report-No.: | Certification Status |
|---|----------|--------------------|----------------------|
| FSoE Application Software Safety Manual R30UZ0143EJ0100 | 1.00 | 968/FSP 2104.00/20 | <i>Valid</i> |
| FSoE Application Software for EWRX User Guide R30UZ0145EJ0100 | 1.00 | | <i>Valid</i> |
| FSoE Application Software for CC-RX User Guide R30UZ0144EJ0100 | 1.00 | | <i>Valid</i> |

The content of this Revision List has been agreed between Manufacturer and Certification Body.

Revision:

| Date | Rev. | Description / Changes | Author |
|------------|------|--|---------|
| 2020-09-18 | 1.0 | Initial creation, based on Report-No.: 968/FSP 2104.00/20. | hs/A-FS |

Renesas Electronics Corporation
3-2-24 Toyosu
Koto-ku
Tokyo 135-0061
Japan

TÜV Rheinland Industrie Service GmbH
Automation - Functional Safety (A-FS)
Am Grauen Stein
51105 Köln / Germany