

Microcomputer Technical Information

CP(K), O

IE-789234-NS-EM1, QB-78K0SKX1MINI Development Tools for Low Pin Count Microcontrollers Document Correction	Document No.	ZBG-CD-06-0059	1/1
	Date issued	July 12, 2006	
	Issued by	Development Tool Group Multipurpose Microcomputer Systems Division 4th Systems Operations Unit NEC Electronics Corporation	
Related documents IE-789234-NS-EM1 User's Manual: U17381EJ4V0UM00 (4th edition) QB-78K0SKX1MINI User's Manual: U17272EJ2V0UM00 (2nd edition)	Notification classification		Usage restriction
			Upgrade
		√	Document modification
			Other notification

1. Affected products

Affected Product	Outline
IE-789234-NS-EM1	Development tool for low pin count microcontrollers (emulation board)
QB-78K0SKX1MINI	Development tool for low pin count microcontrollers (in-circuit emulator)

2. Correction details

Location:

Table 3-2 on p. 20 in IE-789234-NS-EM1 User's Manual (U17381EJ4V0UM00, 4th edition)

Table 2-1 on p. 25 in QB-78K0SKX1MINI User's Manual (U17272EJ2V0UM00, 2nd edition)

Description:

The pin numbers corresponding to the V_{DD} and V_{SS} pins in the 78K0S/KY1+ are incorrect.

Incorrect:		78K0S/KY1+ (16-Pin)	Correct:		78K0S/KY1+ (16-Pin)
	11	V_{DD} (4)		11	V_{DD} (5)
	12	V_{SS} (5)		12	V_{SS} (4)

3. Action

The correction described above will be included in the next revision of the user's manual.

IE-789234-NS-EM1 User's Manual (U17381EJ5V0UM00, 5th edition): Late July, 2006

QB-78K0SKX1MINI User's Manual (U17272EJ3V0UM00, 3rd edition): Late July, 2006