

RENESAS TOOL NEWS on July 16, 2005: RSO-TOOL_1-050716D

A Correction to E8 Emulator Additional Document for User's Manual Notes on Connecting the H8/38076RF and H8/38086RF

We notify a correction to E8 Emulator Additional Document for User's Manual, Notes on Connecting the H8/38076RF and H8/38086RF (Document No. REJ10B0213-0100).

1. Page 7, the first line

Read

The emulator need to use the RES# pin. So build the circuit shown in Figure 3.4 in order that the emulator can accept reset inputs.

for

The RES# pin is used by the emulator. Create the following circuit by connecting the open-collector output buffer so that reset input can be accepted from the emulator.

2. Schedule of Revising the Manual

We plan to revise this misdescription in the next revision of the manual.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.