

RENESAS TOOL NEWS on January 18, 2008: 080118/tn1

High-performance Embedded Workshop Revised to V.4.04.01

High-performance Embedded Workshop (IDE) has been revised from V.4.04.00 to V.4.04.01.

1. Product and Versions to Be Updated

High-performance Embedded Workshop V.3.00.00 through V.4.04.00

High-performance Embedded Workshop is bundled with the compilers and other software products that it manages.

To check for the version number of your High-performance Embedded Workshop, open the Help menu and select the About High-performance Embedded Workshop command.

2. Description of Revision

The following problem has been fixed:

When your High-performance Embedded Workshop updated to V.4.04.00 is launched, it may be terminated abnormally.

For details see RENESAS TOOL NEWS Document No. 080110/tn1, published on January 10, 2008, at

<http://tool-support.renesas.com/eng/toolnews/080110/tn1.htm>

3. How to Update Your Product

Free-of-charge online update is available. Use either of the following ways to update yours:

(1) Download the update program* of the product from the Web site shown below and execute it.

http://www.renesas.com/hew_download

This Web site will be opened from January 21 on.

(2) Use AutoUpdate Utility** to download the update program of the product; then execute it.

This service will be provided on and after January 22.

Note that the above two ways of updating do not update any components

except High-performance Embedded Workshop; that is, no C compilers, emulator debuggers, and others updated.

NOTES:

*Three types of update program are available. Use any of them depending on the IDE you are using. They are as follows:

(a) Full update program

The components of High-performance Embedded Workshop to which changes have been made in and after V.3.00.00 are updated; that is, V.3.00.00 and later can be updated.

(b) Differential update program from V.4.04.00

The components of High-performance Embedded Workshop to which changes have been made in and after V.4.04.00 are updated; that is, V.4.04.00 can be updated.

(c) Differential update program from V.4.03.00

The components of High-performance Embedded Workshop to which changes have been made in and after V.4.03.00 are updated; that is, V.4.03.00 and later can be updated.

**When you are using AutoUpdate Utility whose version falls in a range from V.1.00.00 to V.1.03.00, update it to V.1.04.00; then update your High-performance Embedded Workshop to V.4.04.01. AutoUpdate Utility was revised to V.1.04.00 on July 1, 2007. For details see RENESAS TOOL NEWS Document No. 070701/tn1, published on July 1, 2007, at <http://tool-support.renesas.com/eng/toolnews/070701/tn1.htm>

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.