

RENESAS TOOL NEWS on June 16, 2015: 150616/tn11

Revision of the Applilet3 Coding Assistance Tool for RL78

We are revising Applilet3 for RL78 from V1.07.00 to V1.08.00.

1. Descriptions of Revision

- Modification of defect

The previous version output incorrect values to the option byte LVIMDS1 (used to set the interrupt mode of the power detection circuit), so we have modified the code to output correct values. Change your product to version V1.08.00 if you are using the code generator and any of the target MCUs. Refer to the release note which is installed along with the product for details.

Target MCUs

RL78 family: RL78/F13, RL78/F14, RL78/L12, and RL78/G1A groups

2. Obtaining the Product

Download the installer from the URL below to install the program.

The program will be available from June 22.

https://www.renesas.com/applilet_download

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.