

RENESAS TOOL NEWS on April 16, 2015: 150416/tn7

Revision of Applilet3 for RL78

Applilet3 for RL78 will be updated from V1.06.00 to V1.07.00.

1. Description of Revision

Revised from V1.06.00 to V1.07.00

The following revisions will be made in V1.07.00.

- (a) The problem on the following point announced in a cautionary note (issue No. 140816/tn6 of Renesas Tool News) will be fixed.

With setting of port 1 (target: RL78/G14 group)

For that issue of Tool News, giving more information on the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=140816tn6>

- (b) The problems announced in cautionary notes 1 and 2 (in issue No. 141216/tn5 of Renesas Tool News) will be fixed.

1. Code Generated for Comparator Settings

(Applicable Products: RL78/I1A Group)

2. DTC Settings

(Applicable Products: RL78/F13, RL78/F14 Groups)

For that issue of Tool News, giving more information on the problem, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=141216tn5>

2. Obtaining the Product

Download the installer from the URL below to install the program.

The program will be available from April 20.

https://www.renesas.com/applilet_download

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.