

RENESAS TOOL NEWS on June 16, 2015: 150616/tn5

RX Code Generator for CS+ Revised

We are revising the RX Code Generator for CS+ (CS+ Code_Generator for RX) from V1.06.00 to V1.07.00.

1. Products Concerned

RX code generator for CS+ V1.06.00
(CS+ Code_Generator for RX)

2. Descriptions of Revision

(a) Addition of supported MCUs

The following group has been added to the set of supported MCUs.
RX family: RX23T group

(b) The problems on the following points announced in a cautionary note (issue No. 150301/tn2 of Renesas Tool News) will be fixed.

The problems regarding the points below will be fixed.

1. Multifunction Timer Pulse Unit 3

Applicable products: RX64M group

2. Serial Communications Interface

Applicable products: RX111, RX113, RX64M and RX71M groups

For details of the problems, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150301tn2>

(c) The problems on the following points announced in a cautionary note (issue No. 150516/tn1 of Renesas Tool News) will be fixed.

The problems regarding the points below will be fixed. Numbers 4 and 5 are not yet fixed.

1. Code Generated for the Clock Generation Circuit (PLL Circuit Operation)

Applicable products: RX111 and RX113 groups

2. Bus Settings

Applicable products: RX64M and RX71M groups

3. 16-bit Timer Pulse Unit (TPUa) and Multifunction Timer Pulse Unit3 (MTU3a)

Applicable products: RX64M and RX71M groups

For details of the problems, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150516tn1>

3. Updating Your Product

Online updating is available free of charge.

To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

If your product is CS+ V3.00.00 or an earlier version, you will need to update your CS+ to V3.01.00 in advance.

Please download and install the evaluation edition of CS+ V3.01.00 from the following URL:

https://www.renesas.com/cs+_download

(1) Use the Update Manager

On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager.

This service will be available on and after June 22.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, attempting to run the Update Manager produces an error and the following message.

M0120001

Installation is suspended because CS+ W.exe is running.

It will be resumed next time you start the tool.

(2) Download the installer of the product from our Web site

Download CS+ Code_Generator for RX V1.07.00 from the URL below to install the program.

The program will be available from June 22.

https://www.renesas.com/cs+_download

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.