
[Upgrade to revision]

R20TS0035EJ0100

Rev.1.00

Jun. 16. 2016

Device Information (Managed by CS+) for RH850 Family

Revised to V4.00.01

Outline

We are revising the device information file (managed by CS+) for the RH850 family of MCUs and accordingly will change the version number from V4.00.00 to V4.00.01.

1. Products and Versions to Be Updated

- Device information file managed by CS+ for the RH850 family of MCUs (CS+ Device Information for RH850) V3.00.00 or later
- Device information file managed by CubeSuite+ for the RH850 family of MCUs (CubeSuite+ DevInfo_RH850) V1.00.04 or earlier

Check your version number of “CS+ Device Information for RH850” or “CubeSuite+ DevInfo_RH850” with reference to the procedure described under the heading “Components” at the URL below.

<https://www.renesas.com/products/software-tools/tools/ide/csplus.html#designSupport>

2. Description of Revision

The following is the description of the change in the new revision. For details, go to:

http://www.renesas.com/cubesuite+/CubeSuitePlus_DevInfo_RH850.html

2.1 Addition of Supported MCUs

The following groups have been added to the set of supported MCUs.

- RH850/E1M-S2 group
- RH850/F1H group
- RH850/P1H-C group

2.2 Details of the Correction

- (1) Correction to SFR Information

SFR information for the groups listed below will be corrected.

- RH850/P1H-C group
- RH850/P1M-C group

- (2) Correction to Debugging Information

Debugging information for the group listed below will be corrected.

- RH850/P1M group

2.3 Addition to the Debugging Tools

E1/E20 emulator support for the group listed below will become available.

The simulator already supports this group.

- RH850/F1K group

3. Updating Your Product

Online updating is available free of charge.

To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

- (1) On the “Start” menu, select “Programs” and then “Renesas Electronics CS+” to start the Update Manager. This service will be available from June 20.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

Installation is suspended because “CubeSuiteW+.exe” is running.

It will be resumed next time you start the tool.

- (2) Download and install V4.00.01 of device information file managed by CS+ for the RH850 family of MCUs from the following URL. The program will be available from June 20.

<https://www.renesas.com/products/software-tools/tools/ide/csplus.html#downloads>

3.2 For CubeSuite+ V2.02.01 and Earlier Versions

Please download and install the evaluation edition of CS+ V3.03.00 from the following URL:

<https://www.renesas.com/products/software-tools/tools/ide/csplus.html#downloads>

Then, update your program by using the method in 3.1 (1) or (2) above.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jun. 16, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
 Renesas Electronics Corporation

■Inquiry

<http://www.renesas.com/en-hq/support/contact.html>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.