[Upgrade to revision]

RH850 Smart Configurator V1.3.0

R20TS0657EJ0100 Rev.1.00 Jan. 16, 2021

Overview

The product in the title will be revised and its version number will be changed as follows:

(1) RH850 Smart Configurator: V1.2.0 to V1.3.0

1. Version to Be Updated

All revisions up to V1.2.0 of RH850 Smart Configurator

Items Revised

The major revision points are as follows. Refer to the following release note for details.

https://www.renesas.com/software-tool/smart-configurator#documents

RH850 Smart Configurator V1.3.0 Release Note. This information will be released on January 20.

2.1 Description of Modification

The problems regarding the points below have been fixed.

- (1) RENESAS TOOL NEWS, Document No. R20TS0569EC0100, R20TS0576EC0100
- 1. When Using CSI Master and CSI Slave

Applicable devices: RH850/F1KM-S1 group: 48-pin, 64-pin, 80-pin, and 100-pin products

RH850/F1KM-S4 group: 100-pin, 144-pin, 176-pin, and 233-pin products

For details about the problems, refer to the following URL:

https://www.renesas.com/document/tnn/notes-smart-configurator-rh850-2

https://www.renesas.com/document/tnn/notes-smart-configurator-rh850-3

3. How to Update Your Copy

To update your program, use either of the following methods:

(1) For online updating of CS+, refer to section 4, "How to Update Your Copy" in the following Tool News. The program will be available from January 20.

https://www.renesas.com/software-tool/smart-configurator#documents

RENESAS TOOL NEWS, January 16, Document No. R20TS0648E0100

[Upgrade to revision] CS+ Integrated development Environment V8.05.00

(2) Download RH850 Smart Configurator from the following URL, and then install the program.

The program will be available from January 20.

https://www.renesas.com/software-tool/smart-configurator#documents

RH850 Smart Configurator RH850 V1.3.0



Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jan.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu, Koto-ku, Tokyo 135- 0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

 $\hbox{@ 2021 Renesas Electronics Corporation.}$ All rights reserved.

TS Colophon 4.2