

[Notes]

R20TS0364EJ0100

Rev.1.00

Nov. 01, 2018

---

## CS+ Integrated Development Environment

---

### Outline

When using the CS+ integrated development environment, note the following point.

1. Information on the IOR/SFR will no longer be displayed in the Smart Manual of CS+ for CC V6.00.00 and V6.01.00

### 1. Information on the IOR/SFR will no longer be displayed in the Smart Manual of CS+ for CC V6.00.00 and V6.01.00

#### 1.1 Applicable Products

- CS+ for CC V6.00.00 and V6.01.00
- [Evaluation software] CS+ for CC V6.00.00 and V6.01.00
  - The latest version CS+ for CC V7.00.00 is not applicable.

#### 1.2 Applicable MCUs

- RX family and RL78 family MCUs that support the Smart Manual

RH850 family is not applicable as it does not support the Smart Manual.

#### 1.3 Details

Due to changes in security settings of the web server used by CS+, information on the IOR/SFR will no longer be displayed in the Smart Manual panel as of December 28, 2018.

Note that the information on the API functions generated by the code generator continues to be displayed.

#### 1.4 Conditions

- (1) If you have used the Smart Manual before December 28, 2018

Downloaded data for the Smart Manual is saved in the project folder for each project that uses the Smart Manual. If this data is still saved in the folder, the information on the IOR/SFR continues to be displayed in the Smart Manual panel using this data.

Although new data cannot be downloaded, no error messages will be output.

- (2) If you start using the Smart Manual on or after December 28, 2018

As data for the Smart Manual can no longer be downloaded and no data is saved in the folder, the error message, "Display data not exists" will be output in the Smart Manual panel.

## 1.5 Workaround

To avoid this problem, use the following method.

Apply the Microsoft module below:

Microsoft Security Advisory 2960358

URL:<https://docs.microsoft.com/en-us/security-updates/securityadvisories/2015/2960358>

Note: As the settings of all .NET applications will be changed, the network-related functions may become unavailable in some .NET applications.

## 1.6 Schedule for Fixing the Problem

The following products released in July 2018 are designed to support the changes in security settings of the web server. Upgrade your products to the following versions.

- CS+ for CC V7.00.00
- [Evaluation software] CS+ for CC V7.00.00

**Revision History**

| Rev. | Date          | Description |                      |
|------|---------------|-------------|----------------------|
|      |               | Page        | Summary              |
| 1.00 | Nov. 01, 2018 | -           | First edition issued |
|      |               |             |                      |

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan  
 Renesas Electronics Corporation

■Inquiry

<https://www.renesas.com/contact/>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.