[Notes]

RX Family

R20TS0584EJ0100 Rev.1.00 Jun. 01, 2020

RTC Module Firmware Integration Technology

Outline

When using the product in the title, note the following point.

1. Adding a FIT module to a project in e² studio

1. Adding a FIT Module to a Project in e² studio

1.1 Applicable Products

RTC module Firmware Integration Technology (RTC FIT module)

The applicable revision numbers and document numbers are as follows.

Table 1.1 RTC FIT module applicable products

RTC FIT module revision number	Document number
Rev.2.78	R01AN1817EJ0278

1.2 Applicable Devices

RX110, RX111, RX113, and RX130 groups

RX231/RX230, and RX23W groups

RX64M, RX65N/RX651, and RX66N groups

RX71M, RX72M, and RX72N groups

1.3 Details and Conditions

If you download the RTC FIT module from e² studio, the downloaded RTC FIT module does not appear in the Smart Configurator window for adding components. Therefore, the RTC FIT module cannot be added to a project.

1.4 Workaround

The RTC FIT module (Rev.2.78) is also included in the following RX Driver Package.

The RTC FIT module downloaded from the RX Driver Package does appear in the Smart Configurator window for adding components. Therefore, download the RX Driver Package and add the RTC FIT module.

Table 1.2 Products which include the RTC FIT module (Rev.2.78)

RX Driver Package	RX Driver Package	
product name	revision number	Document number
RX Family	Rev.1.26	R01AN5401EJ0126
RX Driver Package Ver.1.26		

1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version.

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jun.01.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu, Koto-ku, Tokyo 135- 0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

 $\hbox{@}$ 2020 Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.1