
PRODUCT CHANGE NOTICE

Manufacturing Site Change for the Listed Intersil Products

**Refer to:
PCN12084**

Date: October 16, 2012

October 16, 2012

To: Our Valued Intersil Customer

Subject: **Manufacturing Site Change for the Listed Intersil Products – Carsem (CAS) Ipoh Malaysia**

This notice is to inform you that Intersil is qualifying the Carsem (CAS) facility located in Ipoh, Malaysia for performing final electrical test, tape and reel, packing, and shipping of the listed packaged products. Intersil will discontinue the use of the current facility, Unisem, upon expiration of the ninety day period outlined in this notice. The products and site-specific verification activities are in progress and scheduled to complete in November 2012.

The Carsem (CAS) facility is ISO 9001:2008 and ISO/TS 16949:2009 certified and currently qualified as a primary supplier to Intersil for testing of packaged products. The following summarizes the activities that will be conducted prior to production release to confirm there is no impact to form, fit, function, or interchangeability of the product.

- Intersil supplied test software and product specific hardware will be used at CAS.
- The test equipment validation plan involves the testing of control units and a correlation lot of select products at the CAS and current facility. The list of products selected as qualification vehicles for this activity is included on the next page.
 - Control units will be tested at the current test site and retested at CAS, their performance recorded, and the results analyzed to validate the set-up.
 - A correlation lot of approximately 1000 units will be tested at the current test site and retested at CAS. The test results from each site will be compared.
 - Continuous monitoring and comparison of the data from lots processed at multiple sites are an ongoing function of the responsible product engineers.
- The visual/mechanical inspection and tape and reel operations are compliant to JEDEC industry standards used by all Intersil subcontractors.

Product affected by this change is identifiable via Intersil's internal traceability system

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product manufactured at the CAS facility beginning *ninety* days from the date of this notification or upon depletion of existing inventory.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster
Intersil Corporation

PCN12084

CC: J. Touvell J. Rauchfuss D. Foster N. Anantharajah A. Yoong L. Teo

List of Qualification Vehicles for Site Verification / Correlation

- EL7212CNZ*
- ISL1557IRZ*
- ISL24020IHTZ*
- ISL28107FUZ*
- ISL28248FBZ*
- ISL55016IRTZ*
- ISL59833IAZ*
- ISL59837IAZ*

Products Affected – PCN12084

| | | | |
|---------------------|-------------------|-----------------|---------------------|
| EL1516AIYZ-T13 | EL5127CYZ-T7 | EL5172IYZ | EL5236IYZ-T7 |
| EL1516AIYZ-T7 | EL5160ISZ | EL5172IYZ-T13 | EL5237IYZ |
| EL1516ISZ-T13 | EL5160ISZ-T13 | EL5172IYZ-T7 | EL5237IYZ-T13 |
| EL1516ISZ-T7 | EL5160ISZ-T7 | EL5173ISZ | EL5237IYZ-T7 |
| EL1516IYZ-T13 | EL5160ISZ-T7A | EL5173ISZ-T13 | EL5263ISZ |
| EL1516IYZ-T7 | EL5160IWZ-T7 | EL5173ISZ-T7 | EL5263ISZ-T13 |
| EL2227CSZ | EL5160IWZ-T7A | EL5173IYZ | EL5263ISZ-T7 |
| EL2227CSZ-T13 | EL5161IWZ-T7 | EL5173IYZ-T13 | EL5306ISZ |
| EL2227CSZ-T7 | EL5161IWZ-T7A | EL5173IYZ-T7 | EL5306ISZ-T13 |
| EL2250CSZ | EL5162ISZ | EL5174ISZ | EL5306ISZ-T7 |
| EL2250CSZ-T13 | EL5162ISZ-T13 | EL5174ISZ-T13 | EL5306IUZ |
| EL2250CSZ-T7 | EL5162ISZ-T7 | EL5174ISZ-T7 | EL5306IUZ-T13 |
| EL2276CSZ | EL5162ISZ-T7A | EL5202IYZ | EL5306IUZ-T7 |
| EL2276CSZ-T13 | EL5162IWZ-T7 | EL5202IYZ-T13 | EL5306IUZ-T7S2490 |
| EL2276CSZ-T7 | EL5162IWZ-T7A | EL5202IYZ-T7 | EL5308IUZ |
| EL4340IUZ | EL5163ICZ-T7 | EL5203ISZ | EL5308IUZ-T13 |
| EL4340IUZ-T13 | EL5163ICZ-T7A | EL5203ISZ-T13 | EL5308IUZ-T7 |
| EL4340IUZ-T7 | EL5163IWZ-T7 | EL5203ISZ-T7 | EL5308IUZ-T7S2490 |
| EL4342ILZA | EL5163IWZ-T7A | EL5203IYZ | EL5324IREZ |
| EL4342ILZA-T13 | EL5164ISZ | EL5203IYZ-T13 | EL5324IREZ-T13 |
| EL4342ILZA-T13S2714 | EL5164ISZ-T13 | EL5203IYZ-T7 | EL5324IREZ-T7 |
| EL4342ILZA-T7 | EL5164ISZ-T7 | EL5204IYZ | EL5325AIREZ |
| EL4342ILZA-T7S2490 | EL5164IWZ-T7 | EL5204IYZ-T13 | EL5325AIREZ-T13 |
| EL4342ILZA-T7S2714 | EL5164IWZ-T7A | EL5204IYZ-T7 | EL5325AIREZ-T7 |
| EL4543ILZ | EL5165IWZ-T7 | EL5205ISZ | EL5325IREZ |
| EL4543ILZS2714 | EL5165IWZ-T7A | EL5205ISZ-T13 | EL5325IREZ-T7 |
| EL4543ILZ-T13 | EL5166ISZ | EL5205ISZ-T7 | EL5325IRZ |
| EL4543ILZ-T7 | EL5166ISZ-T13 | EL5205IYZ | EL5325IRZ-T13 |
| EL4543ILZ-T7S2714 | EL5166ISZ-T7 | EL5205IYZ-T13 | EL5325IRZ-T7 |
| EL4543IUZ | EL5166IWZ-T7 | EL5205IYZ-T7 | EL5360ISZ |
| EL4543IUZS2714 | EL5166IWZ-T7A | EL5211IYEZ | EL5360ISZ-T13 |
| EL4543IUZ-T13 | EL5166IWZ-T7S2490 | EL5211IYEZ-T13 | EL5360ISZ-T7 |
| EL4543IUZ-T13S2714 | EL5167ICZ-T7 | EL5211IYEZ-T7 | EL5360IUZ |
| EL4543IUZ-T7 | EL5167ICZ-T7A | EL5211TIYEZ | EL5360IUZ-T13 |
| EL5104IWZ-T7 | EL5167IWZ-T7 | EL5211TIYEZ-T13 | EL5360IUZ-T7 |
| EL5104IWZ-T7A | EL5167IWZ-T7A | EL5211TIYEZ-T7 | EL5362ISZ |
| EL5105IWZ-T7 | EL5170ISZ | EL5220CYZ | EL5362ISZ-T13 |
| EL5105IWZ-T7A | EL5170ISZ-T13 | EL5220CYZ-T13 | EL5362ISZ-T7 |
| EL5106ISZ | EL5170ISZ-T7 | EL5220CYZ-T7 | EL5362IUZ |
| EL5106ISZ-T13 | EL5170IYZ | EL5220TIYZ | EL5362IUZ-T13 |
| EL5106ISZ-T7 | EL5170IYZ-T13 | EL5220TIYZ-T13 | EL5362IUZ-T7 |
| EL5106IWZ-T7 | EL5170IYZ-T7 | EL5220TIYZ-T7 | EL5364ISZ |
| EL5106IWZ-T7A | EL5171ISZ | EL5225IRZ | EL5364ISZ-T13 |
| EL5111IYEZ | EL5171ISZ-T13 | EL5225IRZ-T13 | EL5364ISZ-T7 |
| EL5111IYEZ-T13 | EL5171ISZ-T7 | EL5225IRZ-T7 | EL5364IUZ |
| EL5111IYEZ-T7 | EL5171ISZ-T7A | EL5236ISZ | EL5364IUZA |
| EL5111TIWZ-T7 | EL5172ISZ | EL5236ISZ-T13 | EL5364IUZA-T13 |
| EL5111TIWZ-T7A | EL5172ISZ-T13 | EL5236ISZ-T7 | EL5364IUZA-T7 |
| EL5127CYZ | EL5172ISZ-T7 | EL5236IYZ | EL5364IUZA-T7S2490 |
| EL5127CYZ-T13 | EL5172ISZ-T7A | EL5236IYZ-T13 | EL5364IUZA-T7S2490S |

Products Affected – PCN12084 – cont.

| | | | |
|----------------------|--------------------|--------------------|----------------|
| EL5364IUZA-T7S2490S1 | EL5421TIYZ-T13 | EL7202CSZ-T13R5215 | EL7630ICZ-T7A |
| EL5364IUZ-T13 | EL5421TIYZ-T7 | EL7202CSZ-T7 | EL7630IWTZ-T7 |
| EL5364IUZ-T7 | EL5462ISZ | EL7212CSZ | EL7630IWTZ-T7A |
| EL5364IUZ-T7R5289 | EL5462ISZ-T13 | EL7212CSZ-T13 | EL8100ISZ |
| EL5370IUZ | EL5462ISZ-T7 | EL7212CSZ-T7 | EL8100ISZ-T13 |
| EL5370IUZ-T13 | EL5525IREZ | EL7222CSZ | EL8100ISZ-T7 |
| EL5370IUZ-T7 | EL5525IREZ-T13 | EL7222CSZE9044 | EL8100IWZ-T7 |
| EL5372IUZ | EL5525IREZ-T7 | EL7222CSZE9044-T7 | EL8100IWZ-T7A |
| EL5372IUZ-T13 | EL5625ILZ | EL7222CSZ-T13 | EL8101IWZ-T7 |
| EL5372IUZ-T7 | EL5625ILZ-T13 | EL7222CSZ-T7 | EL8101IWZ-T7A |
| EL5373IUZ | EL6140CUZ-T7 | EL7232CSZ | EL8102ISZ |
| EL5373IUZR5293-T7 | EL6145CUZ | EL7232CSZ-T13 | EL8102ISZ-T13 |
| EL5373IUZ-T13 | EL6145CUZ-T13 | EL7232CSZ-T7 | EL8102ISZ-T7 |
| EL5373IUZ-T7 | EL6145CUZ-T7 | EL7252CSZ | EL8102IWZ-T7 |
| EL5374IUZ | EL6196ACLZ | EL7252CSZ-T13 | EL8102IWZ-T7A |
| EL5374IUZ-T13 | EL6196ACLZ-T13 | EL7252CSZ-T7 | EL8103IWZ-T7 |
| EL5374IUZ-T7 | EL6196ACLZ-T7 | EL7457CLZ | EL8103IWZ-T7A |
| EL5375IUZ | EL6201CWZ-T7 | EL7457CLZR5251 | EL8108ILZ |
| EL5375IUZ-T13 | EL6201CWZ-T7A | EL7457CLZ-T13 | EL8108ILZ-T13 |
| EL5375IUZ-T7 | EL6201CYZ-T13 | EL7457CLZ-T13R5251 | EL8108ILZ-T7 |
| EL5378IUZ | EL6201CYZ-T7 | EL7457CLZ-T7 | EL8108ISZ |
| EL5378IUZ-T13 | EL6204CWZ-T7 | EL7457CLZ-T7A | EL8108ISZ-T13 |
| EL5378IUZ-T7 | EL6204CWZ-T7A | EL7457CLZ-T7R5251 | EL8108ISZ-T7 |
| EL5411IREZ | EL6215CUZ | EL7457CSZ | EL8170FSZ |
| EL5411IREZ-T13 | EL6215CUZ-T13 | EL7457CSZ-T13 | EL8170FSZ-T7 |
| EL5411IREZ-T13R5379 | EL6215CUZ-T7 | EL7457CSZ-T7 | EL8170FSZ-T7A |
| EL5411IREZ-T7 | EL6243CUZ-T13 | EL7457CSZ-T7A | EL8171FSZ |
| EL5411IREZ-T7R5379 | EL6273CUZ | EL7457CUZ | EL8171FSZ-T7 |
| EL5411IRZ | EL6273CUZ-T13 | EL7457CUZ-T13 | EL8172FSZ |
| EL5411IRZ-T13 | EL6912CLZ-T13 | EL7457CUZ-T7 | EL8172FSZ-T7 |
| EL5411IRZ-T7 | EL6915CLZ-T13 | EL7457CUZ-T7A | EL8172FSZ-T7A |
| EL5411TILZ | EL6915CLZ-T7 | EL7520AILZ | EL8173FSZ |
| EL5411TILZ-T13 | EL6934ACLZ-T13 | EL7520AILZ-T13 | EL8173FSZ-T7 |
| EL5411TILZ-T7 | EL6934CLZE9054-T13 | EL7520AILZ-T7 | EL8176FSZ |
| EL5411TIREZ | EL7104CSZ | EL7520ILZ | EL8176FSZ-T7 |
| EL5411TIREZ-T13 | EL7104CSZ-T13 | EL7520ILZ-T13 | EL8176FWZ-T7 |
| EL5411TIREZ-T7 | EL7104CSZ-T7 | EL7520ILZ-T7 | EL8176FWZ-T7A |
| EL5420CSZ | EL7154CSZ | EL7551CU-T13 | EL8201ISZ |
| EL5420CSZ-T13 | EL7154CSZ-T13 | EL7551CU-T7 | EL8201ISZ-T13 |
| EL5420CSZ-T7 | EL7154CSZ-T7 | EL7551CUZ | EL8201ISZ-T7 |
| EL5420TILZ | EL7155CSZ | EL7551CUZ-T13 | EL8302ISZ |
| EL5420TILZ-T13 | EL7155CSZ-T13 | EL7551CUZ-T13S2705 | EL8302ISZ-T13 |
| EL5420TILZ-T7 | EL7155CSZ-T7 | EL7551CUZ-T7 | EL8302ISZ-T7 |
| EL5420TISZ | EL7156CSZ | EL7586AILZ | EL8302IUZ |
| EL5420TISZ-T13 | EL7156CSZ-T13 | EL7586AILZ-T13 | EL8302IUZ-T13 |
| EL5420TISZ-T7 | EL7156CSZ-T7 | EL7586AILZ-T7 | EL8302IUZ-T7 |
| EL5421CYZ | EL7156CSZ-T7A | EL7586ILZ | EL8401ISZ |
| EL5421CYZ-T13 | EL7202CSZ | EL7586ILZ-T13 | EL8401ISZ-T13 |
| EL5421CYZ-T7 | EL7202CSZR5215 | EL7586ILZ-T7 | EL8401ISZ-T7 |
| EL5421TIYZ | EL7202CSZ-T13 | EL7630ICZ-T7 | EL8401IUZ |

Products Affected – PCN12084 – cont.

| | | | |
|--------------------|----------------------|----------------------|-------------------|
| EL8401IUZ-T13 | ISL1535IRZ-T13 | ISL24103IRZ | ISL28108FBZ-T7A |
| EL8401IUZ-T7 | ISL1535IVEZ | ISL24103IRZ-T13 | ISL28108FRTZ |
| EL8403ISZ | ISL1535IVEZR5317 | ISL24202IRTZ | ISL28108FRTZ-T13 |
| EL8403ISZ-T13 | ISL1535IVEZ-T13 | ISL24202IRTZ-T13 | ISL28108FRTZ-T7 |
| EL8403ISZ-T7 | ISL1535IVEZ-T13R5317 | ISL24211IRTZ | ISL28108FRTZ-T7A |
| EL8403IUZ | ISL1539AIRZ | ISL24211IRTZ-T13 | ISL28110FBZ |
| EL8403IUZ-T13 | ISL1539AIRZ-T13 | ISL24212IRTZ | ISL28110FBZ-T13 |
| EL8403IUZ-T7 | ISL1539IRZ | ISL24212IRTZ-T13 | ISL28110FBZ-T7 |
| EL9110IUZ | ISL1539IRZ-T13 | ISL24813IRTZ | ISL28110FBZ-T7A |
| EL9110IUZE9049 | ISL1539IRZ-T7 | ISL24813IRTZ-T13 | ISL28113FEZ-T7 |
| EL9110IUZE9049-T13 | ISL1539IVEZ | ISL24821IRTZ | ISL28113FEZ-T7A |
| EL9110IUZE9049-T7 | ISL1539IVEZ-T13 | ISL24821IRTZ-T13 | ISL28113FHZ-T7 |
| EL9110IUZS2714 | ISL1539IVEZ-T7 | ISL24822IRTZ | ISL28113FHZ-T7A |
| EL9110IUZ-T13 | ISL1550IRZ | ISL24822IRTZ-T13 | ISL28114FEZ-T7 |
| EL9110IUZ-T7 | ISL1550IRZ-T13 | ISL24833IRZ | ISL28114FEZ-T7A |
| EL9111ILZ | ISL1550IRZ-T7 | ISL24833IRZ-T13 | ISL28114FHZ-T7 |
| EL9111ILZ-T13 | ISL1557AIRZ | ISL24837AIRZ | ISL28114FHZ-T7A |
| EL9111ILZ-T7 | ISL1557AIRZ-T7 | ISL24837AIRZ-T13 | ISL28117FBBZ |
| EL9112ILZ | ISL1557AIRZ-T7S2705 | ISL24837IRZ | ISL28117FBBZ-T13 |
| EL9112ILZS2714 | ISL1557AIUEZ | ISL24837IRZ-T13 | ISL28117FBBZ-T7 |
| EL9112ILZ-T13 | ISL1557AIUEZ-T7 | ISL28005FH100Z-T7 | ISL28117FBBZ-T7A |
| EL9112ILZ-T13S2714 | ISL1557IRZ | ISL28005FH100Z-T7A | ISL28117FBZ |
| EL9112ILZ-T7 | ISL1557IRZ-T7 | ISL28005FH20Z-T7 | ISL28117FBZ-T13 |
| EL9112ILZ-T7S2714 | ISL1557IUEZ | ISL28005FH20Z-T7A | ISL28117FBZ-T7 |
| ISL1208IU8Z | ISL1557IUEZ-T7 | ISL28005FH50Z-T7 | ISL28117FBZ-T7A |
| ISL1532AIRZ | ISL1571IRZ | ISL28005FH50Z-T7A | ISL28117FRTBZ |
| ISL1532AIRZ-T13 | ISL1571IRZ-T7 | ISL28006FH100Z-T7 | ISL28117FRTBZ-T13 |
| ISL1532AIRZ-T7 | ISL1571IUEZ | ISL28006FH100Z-T7A | ISL28117FRTBZ-T7 |
| ISL1532AIVEZ | ISL1571IUEZ-T7 | ISL28006FH20Z-T7 | ISL28117FRTBZ-T7A |
| ISL1532AIVEZ-T13 | ISL1572IRZ | ISL28006FH20Z-T7A | ISL28117FRTZ |
| ISL1532AIVEZ-T7 | ISL1572IRZ-T7 | ISL28006FH50Z-T7 | ISL28117FRTZ-T13 |
| ISL1532IRZ | ISL1572IUEZ | ISL28006FH50Z-T7A | ISL28117FRTZ-T7 |
| ISL1532IRZ-T13 | ISL1572IUEZ-T7 | ISL28006FHADJZ-T7 | ISL28117FRTZ-T7A |
| ISL1532IRZ-T7 | ISL21060BFH625Z-TK | ISL28006FHADJZ-T7A | ISL28117FUBZ |
| ISL1532IVEZ | ISL21060BFH630Z-TK | ISL28107FBZ | ISL28117FUBZ-T13 |
| ISL1532IVEZ-T13 | ISL21060CFH625Z-TK | ISL28107FBZ-T13 | ISL28117FUBZ-T7 |
| ISL1532IVEZ-T7 | ISL21060CFH630Z-TK | ISL28107FBZ-T7 | ISL28117FUBZ-T7A |
| ISL1533IRZ | ISL21440IRTZ | ISL28107FBZ-T7A | ISL28117FUZ |
| ISL1533IRZ-T13 | ISL21440IRTZ-T13 | ISL28107FRTZ | ISL28117FUZ-T13 |
| ISL1533IVEZ | ISL24002IRTZ | ISL28107FRTZ-T13 | ISL28117FUZ-T7 |
| ISL1533IVEZ-T13 | ISL24002IRTZ-T13 | ISL28107FRTZ-T7 | ISL28117FUZ-T7A |
| ISL1534IRZ | ISL24016IRTZ | ISL28107FRTZ-T7A | ISL28118FBZ |
| ISL1534IRZ-T13 | ISL24016IRTZ-T13 | ISL28107FUZ | ISL28118FBZ-T13 |
| ISL1534IVEZ | ISL24017IRTZ | ISL28107FUZ-T13 | ISL28118FBZ-T7 |
| ISL1534IVEZ-T13 | ISL24017IRTZ-T13 | ISL28107FUZ-T13S2568 | ISL28118FBZ-T7A |
| ISL1535AIRZ | ISL24020IHTZ-T7 | ISL28107FUZ-T7 | ISL28118FUZ |
| ISL1535AIRZ-T13 | ISL24021IRT065Z-T13 | ISL28107FUZ-T7A | ISL28118FUZ-T13 |
| ISL1535AIVEZ | ISL24021IRT065Z-T7A | ISL28108FBZ | ISL28118FUZ-T7 |
| ISL1535AIVEZ-T13 | ISL24102IRTZ | ISL28108FBZ-T13 | ISL28118FUZ-T7A |
| ISL1535IRZ | ISL24102IRTZ-T13 | ISL28108FBZ-T7 | ISL28118MUZ |

Products Affected – PCN12084 – cont.

| | | | |
|-------------------|---------------------|----------------------|---------------------|
| ISL28118MUZ-T13 | ISL28177FBZ-T7 | ISL28217FRTBZ-T7 | ISL28233FUZ |
| ISL28118MUZ-T7 | ISL28177FBZ-T7A | ISL28217FRTZ | ISL28233FUZ-T7 |
| ISL28118MUZ-T7A | ISL28190FHZ-T7 | ISL28217FRTZ-T13 | ISL28233FUZ-T7A |
| ISL28127FBZ | ISL28191FHZ-T7 | ISL28217FRTZ-T7 | ISL28236FBZ |
| ISL28127FBZ-T13 | ISL28194FHZ-T7 | ISL28217FUZ | ISL28236FBZ-T7 |
| ISL28127FBZ-T7 | ISL28194FHZ-T7A | ISL28217FUZ-T13 | ISL28248FBZ |
| ISL28127FBZ-T7A | ISL28207FBZ | ISL28217FUZ-T7 | ISL28248FBZ-T7 |
| ISL28127FRTBZ | ISL28207FBZ-T13 | ISL28217FUZ-T7A | ISL28248FBZ-T7S2490 |
| ISL28127FRTBZ-T13 | ISL28207FBZ-T7 | ISL28218FBZ | ISL28248FUZ |
| ISL28127FRTBZ-T7 | ISL28207FBZ-T7A | ISL28218FBZ-T13 | ISL28248FUZ-T7 |
| ISL28127FRTBZ-T7A | ISL28207FRTZ | ISL28218FBZ-T7A | ISL28248FUZ-T7S2490 |
| ISL28127FRTZ | ISL28207FRTZ-T13 | ISL28227FBZ | ISL28258FBZ |
| ISL28127FRTZ-T13 | ISL28207FRTZ-T7 | ISL28227FBZ-T13 | ISL28258FBZ-T7 |
| ISL28127FUBZ | ISL28207FUZ | ISL28227FBZ-T7 | ISL28258FUZ |
| ISL28127FUBZ-T13 | ISL28207FUZ-T13 | ISL28227FBZ-T7A | ISL28258FUZ-T7 |
| ISL28127FUBZ-T7 | ISL28207FUZ-T7 | ISL28227FRTBZ | ISL28273FAZ |
| ISL28127FUBZ-T7A | ISL28207FUZ-T7A | ISL28227FRTBZ-T13 | ISL28273FAZ-T7 |
| ISL28127FUZ | ISL28208FBZ | ISL28227FRTZ | ISL28276FBZ |
| ISL28127FUZ-T13 | ISL28208FBZ-T13 | ISL28227FRTZ-T13 | ISL28276FBZ-T7 |
| ISL28127FUZ-T7 | ISL28208FBZ-T7 | ISL28227FUBZ | ISL28276IAZ |
| ISL28127FUZ-T7A | ISL28208FBZ-T7A | ISL28227FUBZ-T13 | ISL28276IAZ-T7 |
| ISL28130CEZ-T7 | ISL28208FBZ-T7S2752 | ISL28227FUBZ-T7 | ISL28288FBZ |
| ISL28130CEZ-T7A | ISL28208FRTZ | ISL28227FUBZ-T7A | ISL28288FBZ-T7 |
| ISL28130CHZ-T7 | ISL28208FRTZ-T13 | ISL28227FUZ | ISL28288FUZ |
| ISL28130CHZ-T7A | ISL28208FRTZ-T7 | ISL28227FUZ-T13 | ISL28288FUZ-T7 |
| ISL28133FEZ-T7 | ISL28208FRTZ-T7A | ISL28227FUZ-T7 | ISL28290FBZ |
| ISL28133FHZ-T7 | ISL28210FBZ | ISL28227FUZ-T7A | ISL28290FBZ-T7 |
| ISL28133FHZ-T7A | ISL28210FBZ-T13 | ISL28230CBZ | ISL28290FUZ |
| ISL28134FHZ-T7 | ISL28210FBZ-T7 | ISL28230CBZ-T7 | ISL28290FUZ-T7 |
| ISL28134FHZ-T7A | ISL28210FBZ-T7A | ISL28230CBZ-T7A | ISL28291FBZ |
| ISL28134IBZ | ISL28213FBZ | ISL28230CRZ | ISL28291FBZ-T7 |
| ISL28134IBZ-T13 | ISL28213FBZ-T13 | ISL28230CRZ-T13 | ISL28291FUZ |
| ISL28134IBZ-T7 | ISL28213FBZ-T7 | ISL28230CRZ-T13R5559 | ISL28291FUZ-T7 |
| ISL28134IBZ-T7A | ISL28213FUZ | ISL28230CRZ-T7 | ISL28325FBZ |
| ISL28136FBZ | ISL28213FUZ-T7 | ISL28230CRZ-T7A | ISL28325FBZ-T13 |
| ISL28136FBZ-T7 | ISL28214FBZ | ISL28230CUZ | ISL28325FBZ-T7 |
| ISL28136FHZ-T7 | ISL28214FBZ-T13 | ISL28230CUZ-T7 | ISL28325FBZ-T7A |
| ISL28136FHZ-T7A | ISL28214FBZ-T7 | ISL28230CUZ-T7A | ISL28325FUZ |
| ISL28148FHZ-T7 | ISL28214FUZ | ISL28230CUZ-T7S2755 | ISL28325FUZ-T13 |
| ISL28148FHZ-T7A | ISL28214FUZ-T7 | ISL28230FBZ | ISL28325FUZ-T7 |
| ISL28156FHZ-T7 | ISL28217FBBZ | ISL28230FBZ-T13 | ISL28325FUZ-T7A |
| ISL28158FBZ | ISL28217FBBZ-T13 | ISL28230FBZ-T7 | ISL28345FBZ |
| ISL28158FBZ-T7 | ISL28217FBBZ-T7 | ISL28230FBZ-T7A | ISL28345FBZ-T13 |
| ISL28158FHZ-T7 | ISL28217FBBZ-T7A | ISL28233FBZ | ISL28345FBZ-T7 |
| ISL28158FHZ-T7A | ISL28217FBZ | ISL28233FBZ-T7 | ISL28345FBZ-T7A |
| ISL28166FHZ-T7 | ISL28217FBZ-T13 | ISL28233FBZ-T7A | ISL28407FBZ |
| ISL28176FBZ | ISL28217FBZ-T7 | ISL28233FRZ | ISL28407FBZ-T13 |
| ISL28176FBZ-T7 | ISL28217FBZ-T7A | ISL28233FRZ-T13 | ISL28407FBZ-T7 |
| ISL28177FBZ | ISL28217FRTBZ | ISL28233FRZ-T7 | ISL28407FBZ-T7A |
| ISL28177FBZ-T13 | ISL28217FRTBZ-T13 | ISL28233FRZ-T7A | ISL28408FBZ |

Products Affected – PCN12084 – cont.

| | | | |
|---------------------|---------------------|---------------------|---------------------|
| ISL28408FBZ-T13 | ISL28915FH6Z-T7 | ISL59112IEZ-T7 | ISL59604IRZ-T7A |
| ISL28408FBZ-T7 | ISL54103IHZ-T7 | ISL59119IBZ | ISL59605IRZ |
| ISL28408FBZ-T7A | ISL54103IHZ-T7A | ISL59119IBZ-T13 | ISL59605IRZ-T7 |
| ISL28408FBZ-T7S2752 | ISL55001IBZ | ISL59311IRZ | ISL59605IRZ-T7A |
| ISL28413FBZ | ISL55001IBZ-T13 | ISL59311IRZ-T13 | ISL59605IRZ-T7S2756 |
| ISL28413FBZ-T13 | ISL55001IBZ-T7 | ISL59420IUZ | ISL59830AIAZ |
| ISL28413FBZ-T7 | ISL55001IBZ-T7A | ISL59420IUZ-T13 | ISL59830AIAZ-T7 |
| ISL28413FVZ | ISL55002IBZ | ISL59420IUZ-T7 | ISL59830IAZ |
| ISL28413FVZ-T13 | ISL55002IBZ-T13 | ISL59421IUZ | ISL59830IAZ-T13 |
| ISL28413FVZ-T7 | ISL55002IBZ-T7 | ISL59421IUZ-T13 | ISL59830IAZ-T7 |
| ISL28414FBZ | ISL55004IBZ | ISL59421IUZ-T7 | ISL59832IRZ |
| ISL28414FBZ-T13 | ISL55004IBZ-T13 | ISL59424IRZ | ISL59833IAZ |
| ISL28414FBZ-T7 | ISL55004IBZ-T7 | ISL59424IRZ-T13 | ISL59833IAZ-T7 |
| ISL28414FVZ | ISL55012IEZ-T7 | ISL59424IRZ-T7 | ISL59833IAZ-T7S2705 |
| ISL28414FVZ-T13 | ISL55014IEZ-T7 | ISL59440IAZ | ISL59834IRZ |
| ISL28414FVZ-T7 | ISL55015IEZ-T7 | ISL59440IAZ-T13 | ISL59837IAZ |
| ISL28417FBBZ | ISL55016IRTZ-T7 | ISL59440IAZ-T7 | ISL59837IAZ-T7 |
| ISL28417FBBZ-T13 | ISL55020IRZ | ISL59441IAZ | ISL59910IRZ |
| ISL28417FBBZ-T7 | ISL55020IRZ-T13 | ISL59441IAZ-T13 | ISL59910IRZ-T7 |
| ISL28417FBBZ-T7A | ISL55036IRTZ | ISL59441IAZ-T7 | ISL59911IRZ |
| ISL28417FBZ | ISL55036IRTZ-T13 | ISL59442IBZ | ISL59911IRZ-T7 |
| ISL28417FBZ-T13 | ISL55190IBZ | ISL59442IBZS2714 | ISL59913IRZ |
| ISL28417FBZ-T7 | ISL55190IBZ-T13 | ISL59442IBZ-T13 | ISL59913IRZ-T7 |
| ISL28417FBZ-T7A | ISL55290IUZ | ISL59442IBZ-T7 | ISL59920IRZ |
| ISL28417FVBZ | ISL55290IUZ-T13 | ISL59442IBZ-T7S2714 | ISL59920IRZ-T7 |
| ISL28417FVBZ-T13 | ISL58113CRZ-T13 | ISL59444IBZ | ISL59921IRZ |
| ISL28417FVBZ-T7 | ISL58115CRZ-T13 | ISL59444IBZ-T13 | ISL59921IRZ-T7 |
| ISL28417FVBZ-T7A | ISL58125CRZ-T13 | ISL59444IBZ-T7 | ISL59922IRZ |
| ISL28417FVZ | ISL58214CRZ | ISL59445IRZ | ISL59922IRZ-T7 |
| ISL28417FVZ-T13 | ISL58214CRZ-T13 | ISL59445IRZ-T13 | ISL59923IRZ |
| ISL28417FVZ-T7 | ISL58706CRZ-T13 | ISL59445IRZ-T7 | ISL59923IRZ-T7 |
| ISL28417FVZ-T7A | ISL58719BCRZ | ISL59446IRZ | ISL85033IRTZ |
| ISL28430CBZ | ISL58719BCRZ-T13 | ISL59446IRZ-T7 | ISL85033IRTZ-T |
| ISL28430CBZ-T7 | ISL58722CRZ-T13 | ISL59446IRZ-T7S2490 | ISL85033IRTZ-T7A |
| ISL28430CBZ-T7A | ISL58725CRZ | ISL59447IRZ-T7S2490 | ISL88011IH522Z-T7A |
| ISL28430CVZ | ISL58725CRZ-T13 | ISL59448IAZ | ISL88011IH522Z-TK |
| ISL28430CVZ-T13 | ISL58731CRTZ-T13 | ISL59448IAZ-T7 | ISL88011IH523Z-T7A |
| ISL28430CVZ-T7A | ISL58781CRZ-T13 | ISL59448IAZ-T7S2490 | ISL88011IH523Z-TK |
| ISL28433FBZ | ISL58792CRTZ | ISL59601IRZ | ISL88011IH526Z-T7A |
| ISL28433FBZ-T7 | ISL58792CRTZ-T13 | ISL59601IRZ-T7 | ISL88011IH526Z-TK |
| ISL28433FBZ-T7A | ISL58792CRTZ-T7A | ISL59601IRZ-T7A | ISL88011IH529Z-T7A |
| ISL28433FVZ | ISL58793CRTZ-T13 | ISL59602IRZ | ISL88011IH529Z-TK |
| ISL28433FVZ-T13 | ISL58797CRTZ-T13 | ISL59602IRZ-T7 | ISL88011IH531Z-T7A |
| ISL28433FVZ-T7A | ISL58831CRZ | ISL59602IRZ-T7A | ISL88011IH531Z-TK |
| ISL28488FVZ | ISL58831CRZ-T13 | ISL59603IRZ | ISL88011IH544Z-T7A |
| ISL28488FVZ-T7 | ISL58838CRZ-T13 | ISL59603IRZ-T7 | ISL88011IH544Z-TK |
| ISL28617FVZ | ISL58955CRZ | ISL59603IRZ-T7A | ISL88011IH546Z-T7A |
| ISL28617FVZ-T13 | ISL58955CRZ-T13 | ISL59603IRZ-T7S2756 | ISL88011IH546Z-TK |
| ISL28617FVZ-T7 | ISL59110IEZ-T7 | ISL59604IRZ | ISL88012IH522Z-T7A |
| ISL28617FVZ-T7A | ISL59110IEZ-T7R5235 | ISL59604IRZ-T7 | ISL88012IH522Z-TK |

Products Affected – PCN12084 – cont.

| | |
|-----------------------|----------------------|
| ISL88012IH523Z-T7A | ISL89411IBZ |
| ISL88012IH523Z-TK | ISL89411IBZ-T13 |
| ISL88012IH526Z-T7A | ISL89412IBZ |
| ISL88012IH526Z-TK | ISL89412IBZ-T13 |
| ISL88012IH529Z-T7A | ISL95210HRZ |
| ISL88012IH529Z-TK | ISL95210HRZ-T |
| ISL88012IH531Z-T7A | ISL95210HRZ-T7A |
| ISL88012IH531Z-TK | ISL95210HRZ-TS2568 |
| ISL88012IH544Z-T7A | ISL95210IRZ |
| ISL88012IH544Z-TK | ISL95210IRZ-T |
| ISL88012IH546Z-T7A | ISL95210IRZ-T7A |
| ISL88012IH546Z-TK | ISL95311UIU10Z |
| ISL88013IH522Z-T7A | ISL95311UIU10Z-TK |
| ISL88013IH522Z-TK | ISL95311WIU10Z |
| ISL88013IH523Z-T7A | ISL95311WIU10Z-TK |
| ISL88013IH523Z-TK | ISL95810UIRT8Z |
| ISL88013IH526Z-T7A | ISL95810UIRT8Z-T |
| ISL88013IH526Z-TK | ISL95810UIU8Z |
| ISL88013IH529Z-T7A | ISL95810UIU8Z-T |
| ISL88013IH529Z-TK | ISL95810UIU8Z-TR5391 |
| ISL88013IH531Z-T7A | ISL95811UFRTZ |
| ISL88013IH531Z-TK | ISL95811UFRTZ-TK |
| ISL88013IH544Z-T7A | ISL95811UFUZ |
| ISL88013IH544Z-TK | ISL95811UFUZ-T |
| ISL88013IH546Z-T7A | ISL95811UFUZ-TK |
| ISL88013IH546Z-TK | ISL95811WFRTZ |
| ISL88014IH5Z-T7A | ISL95811WFRTZ-TK |
| ISL88014IH5Z-TK | ISL95811WFUZ |
| ISL88015IH5Z-T7A | ISL95811WFUZ-T |
| ISL88015IH5Z-TK | ISL95811WFUZ-TK |
| ISL88694IH5Z-TK | ISL97631IHTZ-T7 |
| ISL88694IH5Z-TKS2490 | ISL97631IHTZ-T7A |
| ISL88694IH5Z-TKS2490S | ISL98012IUZ |
| ISL89410IBZ | ISL98012IUZ-T |
| ISL89410IBZ-T13 | ISL98012IUZ-TK |