Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.



HITACHI SEMICONDUCTOR TECHNICAL UPDATE

DATE	24th March, 1999	No.	TN-EML-040A/E
тнеме	Malfunction of TELNET Connection in E8000 Emulator (HS8000EST02SR)		
CLASSIFICATION	⊠ Spec. change		
PRODUCT NAME	HS8000EST02SR (embedded in HS8000EST02H)	Lot No. etc.	V1.0
REFERENCE DOCUMENT	-	Effective Date	Permanent
In the LAN interface of the E8000 emulator (HS8000EST02H), the TELNET may not be correctly connected in a part of workstations (HP9000-series HP-UX 10.20 and SPARC station Solaris 2.5). If the TELNET connection fails when the LAN interface of the E8000 emulator is used, contact Hitachi's sales department. We will improve the revision (V1.0A) of the E8000-monitor software.			
			· i
			· · · · · · · · · · · · · · · · · · ·
	•		