

RENESAS TOOL NEWS on April 1, 2005: RSO-HEW_2-050401D

A Note on Using the High-performance Embedded Workshop --On Creating Assembler Project Workspaces--

Please take note of the following problem in using the High-performance Embedded Workshop, an integrated development environment:

- On creating assembler project workspaces
-

1. Product Concerned

The High-performance Embedded Workshop included in the following product is concerned:

The C/C++ Compiler Package for the H8, H8S and H8SX families V.6.01 Release 00 (Windows version)

2. Description

If assembler project workspaces are created, the message shown below is displayed during working on the New Project dialog box, resulting in no assembler project workspace being created.

Title of Message: hprojgen

Message:

Internal Error

Project Generator failed to run.

3. Workaround

This problem will be resolved by using the device updater to be revised on this April 7. For further information on this device updater, see RENESAS TOOL NEWS "DeviceUpdater (for HEWs Included with the SuperH RISC engine, H8SX, H8S and H8 Family Devices) Revised to V.1.04 Release 00" No. RSO-DeviceUpdater-050401D, issued on April 1, 2005.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.