

## Note on Using Integrated Development Environment CubeSuite+ for V850 Family

When using the CubeSuite+ for the V850 family of MCUs, take note of the following problem:

- With building or downloading a program
- 

### 1. Products Concerned

This problem concerns the following products whose CubeSuite+ Common Program is V2.01.00:

- C Compiler and IDE for V850 Family
- Evaluation edition of CubeSuite+

To check to see the version number, refer to the following URL:

[https://www.renesas.com/cubesuite+\\_ver](https://www.renesas.com/cubesuite+_ver)

The above URL is one of our global sites.

### 2. Description

An application error may sometimes occur during building (see NOTE) or downloading of a program.

When this happens, it forces the user to quit CubeSuite+.

NOTE:

Build operation by rapid build function is also included.

### 3. Condition

Specifically, debugging a load module file created by the CX compiler leads to the error that forces the user to quit. This problem does not arise when debugging a load module file created by the CA850 compiler.

### 4. Solution

This problem will be fixed in the next version of the CubeSuite+ common program group.

If you need to take measures against this problem before the next

release, please consult your local Renesas Electronics marketing office or distributor.

---

**[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.