

RENESAS TOOL NEWS on August 1, 2013: 130801/tn3

Device Information for RL78 Family and 78K MCUs (Managed by CubeSuite+) Revised to V1.00.14

We have revised "CubeSuite+ DevInfo_RL78_78K," the Device Information for the RL78 family and 78K MCUs (managed by CubeSuite+), from V1.00.12 to V1.00.14

1. Product and Versions to Be Updated

CubeSuite+ DevInfo_RL78_78K V1.00.12

To check to see the version number of your product, follow these steps:

For Windows XP:

- (1) On Control Panel of Windows, click Add/Remove Programs.
- (2) In the program list, click the icon of CubeSuite+ DevInfo_RL78_78K.
- (3) Click "Click here for support information."

You see the version number of yours such as V1.00.1291.

Here, neglect the last two digits, 91.

For Windows Vista, Windows 7 and Windows 8:

- (1) On Control Panel of Windows, open "Programs and Features."
- (2) Check the version number of CubeSuite+ DevInfo_RL78_78K in the list. You see it such as V1.00.1291. Here, neglect the last two digits, 91.

2. Description of Revision

(1) Supported MCUs Added

The following MCUs have been added to the support line:

- RL78 family RL78/L1C group
- RL78 family RL78/F14 group:
 - R5F10PGG, R5F10PGH, R5F10PGJ, R5F10PLG,
 - R5F10PLH, R5F10PLJ, R5F10PMG, R5F10PMH,
 - R5F10PMJ, R5F10PPE, R5F10PPF, R5F10PPG,
 - and R5F10PPH

(2) Deletion for the following MCUs

- uPD78F8039 in 78K0:
uPD78F8033, uPD78F8034, uPD78F8035, uPD78F8036,
uPD78F8037, and uPD78F8039

(3) Addition and Modification of SFR Information

- RL78 family RL78/F13 group
R5F10AGF, R5F10AGG, R5F10ALF, R5F10ALG,
R5F10AME, R5F10AMF, and R5F10AMG

(4) Modification of Debug Information

- RL78 family RL78/F13 group
- RL78 family RL78/F14 group

For details of the revision, see:

https://www.renesas.com/cubesuite+/CubeSuitePlus_DevInfo_RL78_78K.html
This Web page will be updated on August 1.

3. Updating Your Product

Online updating is available. To update either your commercial edition or evaluation edition of CubeSuite+, use either of the following methods.

If you are using the common program group of CubeSuite+ V1.03.00 or earlier, please download and install the evaluation edition of CubeSuite+ V2.00.00 from the following URL:

https://www.renesas.com/cs+_download

The above URL is one of our global sites.

(1) Use Update Manager

On the Start menu, select Programs and then Renesas Electronics CubeSuite+ to start the Update Manager.

This service will be available on and after August 1.

Note: If your CubeSuite+ has been launched with the rapid startup enabled, exit the CubeSuite+ once, and then run the Update Manager.

If the CubeSuite+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs with the following message:

M0120001

Installation is suspended because "CubeSuite+W.exe" is running.

It will be resumed next time you start the tool.

(2) Download the installer of the product from our Web site

Download CubeSuite+ DevInfo_RL78_78K V1.00.14 from the following URL:

https://www.renesas.com/cs+_download

Then install it.

The above program will be published on August 1.

The above URL is one of our global sites.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.