

RENESAS TOOL NEWS on April 16, 2012: 120416/tn6

## The Emulator Software for the E10A-USB Emulator HS0005KCU04H and HS0005KCU14H Revised to V.2.02 Release 00

We have revised the emulator software for the E10A-USB emulator HS0005KCU04H and HS0005KCU14H from V.2.01 Release 00 to V.2.02 Release 00. These emulator software and emulator are used to evaluate and debug systems designed with SH2A-DUAL- and SH4A-MULTI-cored MCUs of the SuperH RISC engine family.

---

### 1. Product and Versions to Be Updated

The emulator software for the E10A-USB emulator HS0005KCU04H and HS0005KCU14H V1.0.00 through V.2.01 Release 00

### 2. Descriptions of Revision

The product can run on the 64-bit edition of Windows 7.  
Instead, the compatibility with Windows 2000 has been lost.

### 3. How to Update Your Product

Online update is available free of charge. Update yours in either of the following ways:

- (1) Use AutoUpdate Utility. This service will be available on April 20.  
Note that if you are using the V.1.00 Release 00 product, you cannot use AutoUpdate Utility; instead, follow the steps described in (2).
- (2) Follow these steps:
  - (a) Download the update program of the product (a .zip file) from:  
[https://www.renesas.com/e10a\\_usb\\_download](https://www.renesas.com/e10a_usb_download)

This site will be opened on April 20.

The above URL is one of our global sites.

- (b) Decompress the downloaded .zip file to obtain the installer program and then execute it.

#### **4. Notice**

When the installer program is executed in the development system where High-performance Embedded Workshop V.4.08.00 or earlier resides, it will be updated to V.4.09.00.

---

#### **[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.