

The Emulator Software for the E6000H Emulator Specific to the H8SX MCU Family Revised to V.4.05 Release 00

We have revised the emulator software for the E6000H emulator specific to the H8SX MCU family to V.4.05 Release 00.

1. Product and Versions to Be Updated

Emulator software for the E6000H emulator specific to the H8SX MCU family

V.2.01 Release 00 through V.4.03 Release 00*

*V.4.04 Release 00 is an unassigned number.

2. Description of Revision

The following devices have been added to the support line:

Device Group	Devices
8SX/1638	H8SX/1632, H8SX/1634, H8SX/1638
H8SX/1648	H8SX/1642, H8SX/1644, H8SX/1648
H8SX/1658R	H8SX/1653R, H8SX/1654R, H8SX/1658R
H8SX/1668R	H8SX/1663R, H8SX/1664R, H8SX/1668R

3. How to Update Your Product

Free-of-charge online update is available. Use AutoUpdate Utility; otherwise use the following procedure:

(1) Download the update program of the product (a ZIP file) from

the Web site at

http://www.renesas.com/e6000h_download

This site will be opened from January 21 on.

(2) Decompress the downloaded ZIP file to obtain the installer program HewInstMan.exe and execute it.

4. Notice

If the installer program is executed in the system where High-performance Embedded Workshop V.4.02.00 or earlier resides, it will be upgraded to V.4.03.00.

The Install Manager has been introduced into this product from this version. For detail of the Install Manager, please refer the following URL:

http://www.renesas.com/ide/install_manager

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.